Class 1 Permit Modification Notification

Change in Department of Energy, Carlsbad Field Office Manager

Waste Isolation Pilot Plant Carlsbad, New Mexico

WIPP HWFP #NM4890139088-TSDF

Table of Contents

Transmittal Letter Table of Contents
Acronyms and Abbreviations
Overview of the Permit Modification Notification
Attachment A
Item 1 A-3 Description A-3 Basis A-3 Discussion A-3 Revised Permit Text A-3
Attachment B B-1

Acronyms and Abbreviations

CBFO Carlsbad Field Office

CFR Code of Federal Regulations

DOE Department of Energy

HWFP Hazardous Waste Facility Permit
NMAC New Mexico Administrative Code
NMED New Mexico Environment Department

PMN Permit Modification Notification

RCRA Resource Conservation and Recovery Act TSDF Treatment, Storage and Disposal Facility

WIPP Waste Isolation Pilot Plant
WTS Washington TRU Solutions LLC

Overview of the Permit Modification Notification

This document contains one Class 1 Permit Modification Notification (**PMN**) to the Hazardous Waste Facility Permit (**HWFP**) at the Waste Isolation Pilot Plant (**WIPP**), Permit Number NM4890139088-TSDF hereinafter referred to as the WIPP HWFP.

This PMN is being submitted by the U.S. Department of Energy (**DOE**), Carlsbad Field Office (**CBFO**) and Washington TRU Solutions LLC (**WTS**), collectively referred to as the Permittees, in accordance with the WIPP HWFP, Condition I.B.1 (20.4.1.900 New Mexico Administrative Code (**NMAC**) incorporating Title 40 of the Code of Federal Regulations (40 **CFR**) §270.42(a)). The PMN in this document is necessary to notify the New Mexico Environment Department (**NMED**) of a change in the DOE Manager of the Carlsbad Field Office. This change does not reduce the ability of the Permittees to provide continued protection to human health and the environment.

The requested modification to the WIPP HWFP and related supporting documents are provided in this PMN. The proposed modification to the text of the WIPP HWFP has been identified using a <u>double underline</u> and revision bar in the right hand margin for added information, and a <u>strikeout</u> font for deleted information. All direct quotations are indicated by italicized text.

Attachment A

Description of the Class 1 Permit Modification Notification

 Table 1. Class 1 Hazardous Waste Facility Permit Modification Notification

No.	Affected Permit Section	Item	Category	Attachment A Page #
1	a. Attachment A b. Attachment O	Name Change for the Department of Energy Manager	A.1	A-3

Item 1

Description:

Revise the HWFP to change the Department of Energy, Carlsbad Field Office Acting Manager from Mr. R. Paul Detwiler to Mr. Lloyd L. Piper, II, effective November 5, 2004.

Basis:

The change is administrative and informational in nature and is therefore a Class 1 notification pursuant to 20.4.1.900 NMAC (incorporating 40 CFR 270.42, Appendix I, A.1).

Discussion:

On November 5, 2004, Mr. R. Paul Detwiler was replaced by Mr. Lloyd L. Piper, II, as the Acting Manager and responsible official for the Carlsbad Field Office. This HWFP change is necessary as Mr. Piper becomes the signatory authority for the Department of Energy, Carlsbad Field Office.

Revised Permit Text:

a.1. Attachment A, Section A-1

NAME OF FACILITY: Waste Isolation Pilot Plant

OWNER and CO-OPERATOR: U.S. Department of Energy

P.O. Box 3090

Carlsbad, NM 88221

CO-OPERATOR: Washington TRU Solutions LLC

P.O. Box 2078

Carlsbad, NM 88221

RESPONSIBLE OFFICIALS: R.Paul. Detwiler, Lloyd L. Piper, II, Acting

Manager

DOE/Carlsbad Field Office

Dr. Steven Warren, General Manager Washington TRU Solutions LLC

FACILITY MAILING ADDRESS: U.S. Department of Energy

P.O. Box 3090

Carlsbad, NM 88221

FACILITY LOCATION: 30 miles east of Carlsbad on the Jal

Highway, in Eddy County.

TELEPHONE NUMBER: 505/234-7300

U.S. EPA I.D. NUMBER: NM4890139088

GEOGRAPHIC LOCATION: 32° 22' 30" N

103º 47' 30" W

DATE OPERATIONS BEGAN: November 26, 1999

b.1. Attachment O, Part A Application

A revised Part A Application is included in Attachment B

Attachment B

Attachment O, Part A

	F	or El	PA R Jse O		nal								8	·Ε	P	A													
										Unit	ted S		Envi Vashin					n Ag	ency										
									H	az	ar		us					Pe	rn	nit									
				ceive	ed		-					A	pp				n												
Mo	onth	Da			Yea	ır								Par															
	Facil	thre	EDA	ID N	tumi	bor (Mark	. ''Y' ;	n the	- anr			he Inst		ons b	efore	starti	ing)											
١. ١	acm	ity s	EFA	ID N	unn,	ber (/	Wank	X 11	n trie	арр	гори	late	DOX)			4													
L						ubmis	ssion	1					X	B. Re	evise	d Pa	art A	Sub	miss	ion (Ame	endm	nent	#		_17)
C.	Facil	lity's	EPA	ID N	luml	ber						D.	. Sec	onda	ary II) Nu	mbe	r (If a	appli	cable	e)								
N	М	4	8	9	0	1	3	9	0	8	8											<u></u> '							
11.1	Namo	e of F	acili	ty							1																		
W	A	S	Т	E		<u> </u>	s	0	L	Α	Т	1	0	N		Р	<u> </u>	L	0	Т		Р	L	Α	N	Т			
III.	Faci	lity L	.ocat	ion	(Phy	sical	l add	Iress	not	P.O.	Box	or F	Route	Nur	nber)													
A.	Stree	et																											
3	0		М	L	L	E	s		E	Α	S	Т	'	0	F		С	Α	R	L	S	В	Α	D	<u> </u>	0	N	<u> </u>	
		(Cont	tinue	T	T.	I,	T.	T ,					T																
J	A	L		Н	I	G	H	W	Α	Υ								C4.		7:-	000							<u> </u>	
		Town			1	T.	T	T										Sta			Coc			-					
	A unty (L	Sount	B tv Na		D											N	M	8	8	2	2	1				<u> </u>	
100000000	(If know	nJ					T										Т											1	
0 B	3	d Typ	E	D C. Ge	D	Y	C 1 00	catio	n). Fac	cility	Evi	eten	co Da	ato	
-	nter co		_			E (Deg				secon	nds)	LON	VGITU	JDE (Degra	90S, II	ninute	s & se	conds	2)	+	Moi		Da			Yea		
	F			3	2	2	2		3 C) (1	1	0	3	4			3		w		0	5	1	8	1	9	8 1	1
IV.	Fac	ility l	Maili	ng A	ddre	ess																							
Str	eet c	or P.C	D. Bo	ЭX																									
Р	0		В	0	Х		3	0	9	0																			
Cit	y or	Town	n															Sta	rte	Zip	Coc	de							
С	А	R	L	s	В	Α	D											N	М	8	8	2	2	1		3	0	9	0
٧.	Faci	lity (Cont	act (Pers	on to	o be	cont	acte	d reg	jardi	ng v	vaste	acti	vitie	s at	facili	ity)											
Na	me ((Last))												(Fi	rst)													
Р	ı	Р	E	R											L	L	0	Υ	D										
Jo	b Titl	le													Ph	one	Num	ber	(Area	a Coc	de ar	nd N	umbe	er)					
Α	С	Т	I	N	G		М	Α	N	Α	G	Е	R		5	0	5	_	2 :	3 4	4	_	7	3 (6	ф			
		-				ress ((See	inst	ructi	ons)																			
A.	Con	tact /	Addr g	ess	В.	Stre	et or	P.O	. Box	t .																			
		Х			Р	0		В	0	Х		3	0	9	0							<u> </u>				L		<u> </u>	
Cit	y or	Town	n															Sta	ite	Zip	Coc								
С	A	R	L	S	B	A	D	'	'		'		'		['	N	M	8	8	2	2	1	l — '	3	0	9	0

EPA	ID No	ımbe	r (En	ter fi	om p	age	1)				,						Se	con	dary	ID N	umb	er (E	nter	fron	n pa	ge 1)		
N	M 4	4 8	9	0	1	3	9	0	8	8																		
VII. C	pera	tor In	form	atio	ı (Se	e ins	truc	tions	5)																			
A. Na	ame c	of Op	erato	r																								
U	s	D	E	Р	Α	R	Т	М	E	N	Т		0	F		E	N	Е	R	G	Υ							
Stree	et or I	P.O. E	Зох																									
Р	o	В	To	X		3	0	9	0																			
City	or To	wn															Sta	ite	Z	IP Co	ode							
C .	A F	₹ L	. s	В	A	D											N	М	8	8	2	2	1	_	3	0	9	0
Phor	a Nu	mhor	/An	a Co	de ab	nd N	umh	orl					В.	Oper			C. 0		ge of	Ope		Mont		ate C Day	hang		ear	
	5 5	\neg	- 2	3	4	_	7	3	0	0]			F	1525		Yes			X	٦٢	10110	T	Day	Т	T .	Car	Т
VIII.			00000			uctio																						
A. Na																												
	s	D	_	_	T	R	Т	М	E	N	Т		О	F		E	N	E	R	G	Υ							
Stree		P.O. I	00000																									
Р	οТ	В	То	X	Т	3	0	9	0			Π	Т			Т	Т											Π
City	or To	wn															Sta	ite	Z	IP Co	ode							
c .	A F	R L	S	В	A	D						Π	Τ			Τ	N	М	8	8	2	2	1	<u> </u>	3	0	9	0
Dhar			/^-		da a.								В.	Own	er T	ype	C. 0			Owr				ate C	hang			
Phor 5	0 5	$\overline{}$. 2		4	_	7	3	0	0	1			F	٦		Yes		ndica	X	7	Mont	T	Day	Т		ear	
IX. N	AICS	Code	es (ii	ord	er of	sian	ifica	nce:	star	t in l	eft b	ox)																
First			4	T	Т	3		Τ	1					Third				T				Г						
(Descri	ption)	RE	2000				L MS	_						Descrip								_						
Seco			Г	T	Τ	Т	T	Г	1				١.	ourt				Т	Т	Г	Г	Г	1					
(Descri								_					8 8888	Descrip	000000							_						
X. Ot	her F	nvir	nme	ntal	Porm	ite /	See	inetr	uctio	ne)																		
	ermit		т	intai		ito (000	mou	uome	,,,,		_																
	ter c							B. P	ermit	Nun	nber	r								c	. De	scrip	tion					
	E														T	*	See	App	enc	lix C)1, ⊺	Γabl	e O	1-1				
				_	_	_	\perp	_	_	_	\perp	_		+	\bot	4												
	\vdash		H	+	+	_	+	+	+	+	+	+	+	+	+	+												
	\vdash		H	+	-	-	+	+	+	+	+	+	+	+	+	+												
	\vdash		H	+	+	+	+	+	+	+	+	+	+	+	+	+												
			H				+			+	+	+	+	+	+	十												
							\top			T	\top	\top	\top	\top	\top	十												
				\top				\top	\top	\top	\top	\top	\top	\top	\top	T												

EP	A ID	Nun	ber	(Ent	er fr	om p	age	1)				Se	cond	ary	D N	umb	er (E	nter	from	pag	e 1)	
N	М	4	8	9	0	1	3	9	0	8	8											
ΥI	Mati	iro o	f Ru	eino	e /P	rovi	do a	hrio	fdoe	crin	tion											

The Waste Isolation Pilot Plant (WIPP) is a U.S. Department of Energy facility intended to demonstrate the technical and operational principles involved in the permanent isolation and disposal of defense-generated transuranic waste. For purposes of RCRA, WIPP operations entail receiving, unloading, and transferring radioactive-mixed waste from the surface of the site to the underground hazardous waste management units. Waste will be emplaced in an underground geologic repository horizon located in a deep-bedded salt formation approximately 2,150 feet beneath the surface.

XII. Process Codes and Design Capacities

- PROCESS CODE Enter the code from the list of process codes below that best describes each process to be used at the facility. Thirteen lines are provided for entering codes. If more lines are needed, attach a separate sheet of paper with the additional information. For "other" processes (i.e., D99, S99, T04 and X99), describe the process (including its design capacity) in the space provided in item XIII.
- PROCESS DESIGN CAPACITY For each code entered in column A, enter the capacity of the process.
 - AMOUNT Enter the amount. In a case where design capacity is not applicable (such as in a closure/post-closure or enforcement)
 - action) enter the total amount of waste for that process.

 UNIT OF MEASURE For each amount entered in column B(1), enter the code from the list of unit measure codes below that describes the unit of measure used. Only the units of measure that are listed below should be used.

C. PROCESS TOTAL NUMBER OF UNITS	- Enter the total number of	of units used with	the corresponding process code.
PROCESS MEASURE		PROCESS CODE PROC	APPROPRIATE UNITS OF MEASURE FOR PROCESS CESS DESIGN CAPACITY
Well Disposal Per Day D80 Landfill Acre-feet; Hectare-m Meters; Hectares; Ct D81 Land Treatment Acres or Hectares D82 Ocean Disposal Gallons Per Day or L D83 Surface Impoundment Gallons; Litters; Cubi	ons Per Day; or Liters Ti Ti teter; Acres; Cubic tibic Yards Ti titers Per Day to Meters; or	81 Cement Kiln 82 Lime Kiln 83 Aggregate Kiln 84 Phosphate Kiln 85 Coke Oven 86 Blast Furnace	Gallons Per Day; Liters Per Day; Pounds Per Hour; Short Tons Per Hour; Kilograms Per Hour; Metric Tons Per Day; Metric Tons Per Hour; Short Tons Per Day; Btu Per Hour; Liters Per Hour; Kilograms Per Hour; or Million Btu Per Hour
S02 Tank Storage Gallons; Liters; Cubi S03 Waste Pile Cubic Yards or Cubic Surds or Cubic Surds or Cubic Storage S05 Drip Pad Gallons; Liters; Acre Hectares; or Cubic Yards or Cubic Yards or Cubic Storage S99 Other Storage Any Unit of Measure	ic Meters; or Cubic Yards or Meters; or Cubic Meters; or Cubic Meters; or Cubic Meters; or Meters	Or Refining Furnal Titanium Dioxide Chloride Oxidation Methane Reformin Furnace Pulping Liquor Reformace Combustion Devic In The Recovery O Values From Spen Acid Halogen Acid Furn Other Industrial Fu	Gallons Per Day; Liters Per Day; Pounds Per Hour; Short Tons Covery Per Hour; Kilograms Per Hour; Metric Tons Per Day; Metric Tons De Hour; Short Tons Per Day; Btu Per Hour; Gallons Per Hour; Liters Per Hour; or Million Btu Per Hour Dages De Hour; Or Million Btu Per Hour
Per Hour; Gallons P. Pounds Per Hour; Si Kilograms Per Hour; Metric Tons Per Hour To Surface Impoundment Treatment Per Hour; Gallons P. Per Hour; Gallons P.	Metric Tons Per Day; or ors Per Day; Short Tons der Hour; Liters Per Hour;	Listed in 40 CFR § 4 Containment Build Treatment	ding- Cubic Yards; Cubic Meters; Short Tons Per Hour; Gallons Per Hour; Liters Per Hour; Btu Per Hour; Pounds Per Hour; Short Tons Per Day; Kilograms Per Hour; Metric Tons Per Day; Gallons Per Day; Liters Per Day; Metric Tons Per
Metric Tons Per Hou Short Tons Per Hou Short Tons Per Hou Hour; Gallons Per Ho Per Hour; Pounds Pe Day; Kilograms Per I Liters Per Day; Metri Million Btu Per Hour	; Metric Tons Per Day; or r; Metric Tons Per pur; Liters Per Hour; Btu er Hour; Short Tons Per Hour; Gallons Per Day; c Tons Per Hour; or ers Per Day; Pounds Per	Detonation 02 Mechanical Proces	en Any Unit of Measure Listed Below ssing Short Tons Per Hour; Metric Tons Per Hour; Short Tons Per Day; Metric Tons Per Day; Pounds Per Hour; Kilograms Per Hour; Gallons Per Hour; Liters Per Hour; or Gallons Per Day
Hour; Short Tons Pe Hour; Metric Tons Pe Hour; Short Tons Pe Gallons Per Day; Lite Btu Per Hour T80 Boiler Gallons; Liters; Gall	r Hour; Kilograms Per er Day; Metric Tons Per r Day; Blu Per Hour; ers Per Hour; or Million	03 Thermal Unit 04 Geologic Reposito 99 Other Subpart X	Gallons Per Day; Liters Per Day; Pounds Per Hour; Short Tons Per Hour; Kilograms Per Hour; Metric Tons Per Day; Metric Tons Per Hour; Short Tons Per Day; Btu Per Hour; or Million Btu Per Hour Cubic Yards; Cubic Meters; Acre-feet; Hectare-meter; Gallons; or Liters Any Unit of Measure Listed Below
UNIT OF UNIT OF MEASURE MEASURE CODE Gallons G Gallons Per Hour E Gallons Per Day U Liters L Liters Per Hour H Liters Per Day V	UNIT OF MEASURE Short Tons Per Hour Metric Tons Per Day Metric Tons Per Day Metric Tons Per Day Pounds Per Hour Kilograms Per Hour Million Btu Per Hour	W N S J	UNIT OF UNIT OF MEASURE CODE Cubic Yards

EPA	ID I	Num	ber (Ente	r from page 1)	S	Secondary II	οNι	ımt	oer (Ente	r froi	n pa	ge 1)		
N	М	4	8	9	0 1 3 9 0 8 8					Π						
XII.F	roc	ess (Code	s an	d Design Capabilities (Continued)											
		XAMF		OR (COMPLETING ITEM XII (shown in line number X-1 below): A fa	ıcili	ity has a stor	age	tan	k, wh	ich c	an h	old 53	33.78	8	
Lin			Proce		B. PROCESS DESIGN CAPACITY					cess				fficial	ı	
Nun	nber		Code Hist ab		1. Amount (Specify)		2. Unit Of Measure (Enter code)	N		ai ber nits			Use (only		
х	1	s	0	2	5 3 3 7 8	8	G	О	0	1						
	1	X	0	4	175,600 Total (54,064 in 10 years)		С	0	1	0						
	2				See attached page for additional process information	_										
	3	S	0	1	91.9		С	0	0	1						
	4	_ 		_ 	WHB Container Storage Unit See attached page for additional process information	_				_						
	5	S	0	1	47.1		С	0	0	1						
	6	\Box			Parking Area Container Storage Unit											
	7	$\vdash \vdash$			See attached page for additional process information											
	8	$\vdash \vdash$	\rightarrow													
	9	$\vdash \vdash$	\longrightarrow	\sqcap												
1	0	$\vdash \vdash$	\longrightarrow	\sqcap												
1	1	$\vdash \vdash$	\dashv	\square												
1	2	\vdash	\dashv	\sqcap		—										
1	3	\sqcap	-	$\overline{}$												
					ed to list more than 13 process codes, attach an additional sh er the lines sequentially, taking into account any lines that wi											
					item XIII.	II D.	e used for C)tine.	_	1000	5500	(1.6.,	D33,	555,		
XIII	. Otl	ner P	roce	sses	s (Follow instructions from item XII for D99, S99, T04 and	X9	99 process o	ode	s)							
Lit			Proce		B. PROCESS DESIGN CAPACITY		Process			D. D	escri	ption	Of P	Proce	ss	
			Code n list al		1. Amount (Specify) 2. Unit Of Measure (Enter code)	N	Total Number Of Units									
х	1	т	0	4						In	-situ	Vitri	ficati	on		
	1															
	2															
		Ш		Ш	•											
	3															
	4															

Е	PA II	D Nu	mbe	r (Er	nter	from	pag	e 1)				:	Seco	ndar	y ID	Nun	ber	(Ent	er fro	om p	age	1)	
N	М	4	8	9	0	1	3	9	0	8	8												
v	IV D	necr	intio	n of	Нат	ardo	ue V	Vacto	ve.														

- A. EPA HAZARDOUS WASTE NUMBER Enter the four-digit number from 40 CFR, Part 261 Subpart D of each listed hazardous waste you will handle. For hazardous wastes which are not listed in 40 CFR, Part 261 Subpart D, enter the four-digit number(s) from 40 CFR, Part 261 Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.
- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
- C UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE	CODE
POUNDS	Р	KILOGRAMS	к
TONS	T	METRIC TONS	М

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

D. PROCESSES

1. PROCESS CODES:

For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in item XII A. on page 3 to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed hazardous waste: For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process codes contained in item XII A. on page 3 to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant.

NOTE: THREE SPACES ARE PROVIDED FOR ENTERING PROCESS CODES. IF MORE ARE NEEDED:

- Enter the first two as described above.
- 2. Enter "000" in the extreme right box of item XIV-D(1).
- 3. Use additional sheet, enter line number from previous sheet, and enter additional code(s) in item XIV-E.
- PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form (D.(2)).

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER - Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

- Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B, C and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
- 3. Repeat step 2 for each EPA Hazardous Waste Number that can be used to describe the hazardous waste.

EXAMPLE FOR COMPLETING ITEM XIV (shown in line numbers X-1, X-2, X-3, and X-4 below) - A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

			A. E	PA		B. ESTIMATED	C. UNIT OF									D. F	PROCESS
	ne nber	И	HAZ AST Inter	ENC	D .	ANNUAL QUANTITY OF WASTE	MEASURE (Enter code)		(1) PR	OCE.	ss c	ODE	S (E	nter)		(2) PROCESS DESCRIPTION (If a code is not entered in D(1))
X	1	к	0	5	4	900	р	T 0 3 D 8 0									
х	2	D	0	0	2	400	P	т	0	3	D	8	0				
X	3	D	0	0	1	100	P	T 0 3 D 8 0 T 0 3 D 8 0									
х	4	D	0	0	2												Included With Above

EP/	A ID I	Num	ber ((Ente	er fro	om page 1)								Se	con	dary	ID Number (Enter from page 1)
N	М	4	8	9	0	1 3 9	0 8 8										
XIV	. Des	crip	tion	of H	azar	dous Wastes	(Continued;	use :	addit	tiona	l she	ets	as ne	eces	sary		
				EPA rdous		B. Estimated Annual	C. Unit of Measure								D.	PRO	CESSES
Lii Nun		1	Wast	e No.		Quantity of Waste	(Enter code)	(1) PR	ROCE	ss c	ODE	S (E	nter	code)	(2) PROCESS DESCRIPTION (If a code is not entered in D(1))
	1	U	0	0	2	344	М	Х	0	4	S	0	1	S	0	1	
	2	U	0	1	9	344	М	Х	0	4	S	0	1	S	0	1	
	3	U	0	3	7	344	М	Х	0	4	S	0	1	S	0	1	
	4	U	0	4	3	344	М	Х	0	4	S	0	1	S	0	1	
	5	U	0	4	4	344	М	Х	0	4	S	0	1	S	0	1	
	6	U	0	5	2	344	М	Х	0	4	S	0	1	S	0	1	
	7	U	0	7	0	344	М	Х	0	4	S	0	1	S	0	1	
	8	U	0	7	2	344	М	Χ	0	4	S	0	1	S	0	1	
	9	U	0	7	8	344	М	Х	0	4	S	0	1	S	0	1	
1	0	U	0	7	9	344	М	Х	0	4	S	0	1	S	0	1	
1	1	U	1	0	5	344	М	Х	0	4	S	0	1	S	0	1	
1	2	U	1	2	2	344	М	Х	0	4	S	0	1	S	0	1	
1	3	U	1	3	3	344	М	Х	0	4	S	0	1	S	0	1	
1	4	U	1	5	1	344	М	Х	0	4	S	0	1	S	0	1	
1	5	U	1	5	4	344	М	Х	0	4	S	0	1	S	0	1	
1	6	U	1	5	9	344	М	Х	0	4	S	0	1	S	0	1	
1	7	U	1	9	6	344	М	Х	0	4	S	0	1	s	0	1	
1	8	U	2	0	9	344	М	Х	0	4	S	0	1	S	0	1	
1	9	U	2	1	0	344	М	Х	0	4	S	0	1	S	0	1	
2	0	U	2	2	0	344	М	Х	0	4	S	0	1	S	0	1	
2	1	U	2	2	6	344	М	Х	0	4	S	0	1	S	0	1	
2	2	U	2	2	8	344	М	Х	0	4	S	0	1	S	0	1	
2	3	U	2	3	9	344	М	Х	0	4	S	0	1	S	0	1	
2	4	Р	1	2	0	3.3	М	Х	0	4	S	0	1	S	0	1	
2	5	U	1	3	4	344	М	Х	0	4	S	0	1	S	0	1	
2	6	D	0	3	3	344	М	Х	0	4	S	0	1	S	0	1	
2	7	Р	0	3	0	344	М	Х	0	4	S	0	1	S	0	1	
2	8	Р	0	9	8	344	М	Х	0	4	S	0	1	S	0	1	
2	9	Р	0	9	9	344	М	Х	0	4	S	0	1	S	0	1	
3	0	Р	1	0	6	344	М	Χ	0	4	S	0	1	S	0	1	
3	1	U	0	0	3	344	М	Χ	0	4	S	0	1	S	0	1	
3	2	U	1	0	3	344	М	Χ	0	4	S	0	1	S	0	1	
3	3	U	1	0	8	344	М	Χ	0	4	S	0	1	S	0	1	
3	4																
3	5																

Please print or type with ELIT	E type (12 characters per inch	in the unshaded areas only
--------------------------------	----------	------------------------	----------------------------

EPA ID Number (Enter from page 1)	Secondary ID Number (Enter from page 1)
N M 4 8 9 0 1 3 9 0 8 8	
XV. Map	
Attach to this application a topographic map, or other equivalent map, The map must show the outline of the facility, the location of each of it hazardous waste treatment, storage, or disposal facilities, and each was other surface water bodies in this map area. See instructions for preci	s existing and proposed intake and discharge structures, each of its
XVI. Facility Drawing	
All existing facilities must include a scale drawing of the facility (See instructions for more detail).
XVII. Photographs	
All existing facilities must include photographs (aerial or ground-level) and disposal areas; and sites of future storage, treatment or disposal a	that clearly delineate all existing structures; existing storage, treatment reas (see instructions for more detail).
XVIII. Certification(s)	
I certify under penalty of law that this document and all attacin accordance with a system designed to assure that qualifies submitted. Based on my inquiry of the person or persons who for gathering the information, the information submitted is, to complete. I am aware that there are significant penalties for suand imprisonment for knowing violations.	d personnel properly gather and evaluate the information manage the system, or those persons directly responsible o the best of my knowledge and belief, true, accurate, and
Owner Signature Chulm - L Wa for	Date Signed
Name and Official Tille (Type or print) Lloyd, L. Piper II, Acting Manager, DOE/Carlsbad Field Office	Date Signed
name and Official Life (Type of print)	Date Signed Date Signed
Lloyd, L. Piper II, Acting Manager, DOE/Carlsbad Field Office	
Lloyd, L. Piper II, Acting Manager, DOE/Carlsbad Field Office Owner Signature	
Name and Official Title (Type or print) Lloyd, L. Piper II, Acting Manager, DOE/Carlsbad Field Office Owner Signature Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature	Date Signed Date Signed
Name and Official Title (Type of print) Lloyd, L. Piper II, Acting Manager, DOE/Carlsbad Field Office Owner Signature Name and Official Title (Type of print) Operator Signature Name and Official Title (Type of print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature	Date Signed
Name and Official Title (Type or print) Lloyd, L. Piper II, Acting Manager, DOE/Carlsbad Field Office Owner Signature Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature	Date Signed Date Signed
Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature S. D. Warren, President — Washington TRU Solutions, LLC	Date Signed Date Signed U/10/04 Date Signed Date Signed
Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature S. D. Warren, President — Washington TRU Solutions, LLC XIX. Comments Section XVIII Operator Signature - *See attached "RCRA Part A	Date Signed II/10/04 Date Signed II/19/04 Application Certification"
Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature S. D. Warren, President — Washington TRU Solutions, LLC XIX. Comments Section XVIII Operator Signature - *See attached "RCRA Part A	Date Signed Date Signed 11/10/04 Date Signed 11/19/04 Date S
Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature Stand Difficial Title (Type or print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature Stand Difficial Title (Type or print) S. D. Warren, President — Washington TRU Solutions, LLC XIX. Comments Section XVIII Operator Signature - *See attached "RCRA Part A Previous revisions were submitted on July 9, 199 May 26, 1995; April 12, 1996; May 29, 1996; April	Date Signed Date Signed 11/10/04 Date Signed 11/19/04 Date S
Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature Stand Difficial Title (Type or print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature Stand Difficial Title (Type or print) S. D. Warren, President — Washington TRU Solutions, LLC XIX. Comments Section XVIII Operator Signature - *See attached "RCRA Part A Previous revisions were submitted on July 9, 199 May 26, 1995; April 12, 1996; May 29, 1996; April	Date Signed Date Signed 11/10/04 Date Signed 11/19/04 Date Signed 11/19/04 Date Signed 11/19/04 Date Signed 11/19/04 Date Signed 11/19/04 Date Si
Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature S. D. Warren, President — Washington TRU Solutions, LLC XIX. Comments Section XVIII Operator Signature - *See attached "RCRA Part A Previous revisions were submitted on July 9, 1999 May 26, 1995; April 12, 1996; May 29, 1996; April March 7, 2001; June 18, 2001; December 27, 200	Date Signed Date Signed 11/10/04 Date Signed 11/19/04 Date S
Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Operator Signature Name and Official Title (Type or print) Lloyd L. Piper II, Acting Manager, DOE/Carlsbad Field Office Operator Signature S. D. Warren, President — Washington TRU Solutions, LLC XIX. Comments Section XVIII Operator Signature - *See attached "RCRA Part A Previous revisions were submitted on July 9, 199 May 26, 1995; April 12, 1996; May 29, 1996; April March 7, 2001; June 18, 2001; December 27, 200 2004 and January 15, 2004.	Date Signed Date Signed 11/10/04 Date Signed 11/19/04 Date S

RCRA PART A APPLICATION CERTIFICATION

The U.S. Department of Energy (DOE), through its Carlsbad Field Office, has signed as "owner and operator," and Washington TRU Solutions LLC, the Management and Operating Contractor (MOC), has signed this application for the permitted facility as "cooperator."

The DOE has determined that dual signatures best reflect the actual apportionment of Resource Conservation and Recovery Act (RCRA) responsibilities as follows:

The DOE's RCRA responsibilities are for policy, programmatic directives, funding and scheduling decisions, Waste Isolation Pilot Plant (WIPP) requirements of DOE generator sites, auditing, and oversight of all other parties engaged in work at the WIPP, as well as general oversight.

The MOC's RCRA responsibilities are for certain day-to-day operations (in accordance with general directions given by the DOE and in the Management and Operating Contract as part of its general oversight responsibility), including, but not limited to, the following: certain waste handling, monitoring, record keeping, certain data collection, reporting, technical advice, and contingency planning.

For purposes of the certification required by Title 20 of the New Mexico Administrative Code, Chapter 4, Part 1, Subpart IX, (20.4.1.900 NMAC),incorporating 40 CFR, §270.11(d), the DOE's and the MOC's representatives certify, under penalty of law that this document and all attachments were prepared under their direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on their inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of their knowledge and belief, true, accurate, and complete for their respective areas of responsibility. We are aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Chuan I	Wa for L.P.	
Title: Acting Manager, Carlsbad Field Office		
for:U.S. Department of Energy		
Date: 11/10/04		
Co-Operator Signature: Steve Wave		
Seneral Manager		
Vashington TRU Solution	ons LLC	
1119/04		
	Acting Manager, Carl for: U.S. Department of the Carl pate: ////o/4	